

Log-GFU-834-348489

Monday, 10, June, 2019, 09:02:22:35881

VCDS -- Windows Based VAG/VAS Emulator Running on Windows 10 x64

VCDS Version: 18.9.1.0 (x64) HEX-NET CB: 0.4436.4

Data version: 20190114 DS296.0

www.Ross-Tech.com

VIN: License Plate: GFU-834

Mileage: 348489 Repair Order:

Address 02: Auto Trans                      Labels: 01J-927-156.lbl  
Control Module Part Number: 4B0 910 155 G      HW: 01J 927 156 HH  
Component and/or Version: V30 01J 2.4L 5V RdW 3120  
Software Coding: 0000001  
Work Shop Code: WSC 44552 001 00001  
VCID: A208A6DB7C43585A6B-5184

2 Faults Found:

17090 - Transmission Range Sensor (F125)  
P0706 - 000 - Implausible Signal  
Freeze Frame:  
RPM: 96 /min  
RPM: 0 /min  
RPM: 0 /min  
(no units): 1.0  
Torque: 186.0 Nm  
Temperature: 61.0°C  
T.B. Angle: 0.0°  
Bin. Bits: 0001 0 0

18201 - Transmission Output Speed Sensor 2 (G196)  
P1793 - 000 - No Signal  
Freeze Frame:

-----  
-----

Address 01: Engine                      Labels: 078-907-552-AMM.lbl  
Control Module Part Number: 3B0 907 552 BK  
Component and/or Version: 2.4L V6/5V              G    0002  
Software Coding: 11582  
Work Shop Code: WSC 02334  
Additional Info: WAUZZZ4B64N049836              AUZ7Z0C2487506  
VCID: EE9082EBA81BAC3ABF-5184

3 Faults Found:

16815 - Warm Up Catalyst; Bank 2  
P0431 - 35-10 - Efficiency Below Threshold - Intermittent  
16891 - Idle Control System RPM