

VCDS-Lite  
Windows Based VAG/VAS Emulator  
Version: Release 1.2  
www.Ross-Tech.com

Workshop Code: 000 00000

Self-Diagnosis Log  
Wednesday, 08 March 2023, 08:58:57:51337

VIN Number:   License Plate:  
Mileage:    Repair Order:

Chassis Type: 4D - Audi A8 D2  
Scan: 25,01,03,08,11,15,16,17,18,35,37,45,55,56,57,65,67,75,76,77,02

---

Address 25: Immobilizer   Labels: 4B0-953-234.LBL  
Controller: 4B0 953 234  
Component: IMMO AUZ9Z0V8005539 D03  
Coding: 00000  
Shop #: WSC 00000  
VCID: E0B36B0A735B  
No fault code found.

---

Address 01: Engine   Labels: Redir Fail!  
Controller: 4D0 907 558 D  
Component: 4,2L V8/4V MOTR AT D01  
Coding: 05273  
Shop #: WSC 51217  
VCID: 2E2F4532F90F  
No fault code found.  
Readiness: N/A

---

Address 03: ABS Brakes   Labels: 8E0-614-111-ABS.LBL  
Controller: 8E0 614 111 A  
Component: ABS/EDS 5.3 QUATTRO D00  
Coding: 0273004284  
Shop #: BB 24334  
VCID: 1C4B9FFA9FB3  
No fault code found.

---

Address 08: Auto HVAC   Labels: Redir Fail!  
Controller: 4D0 820 043 E  
Component: D2-KLIMAVOLLAUTOMAT\_D03  
Coding: 00180  
Shop #: WSC 00000  
VCID: 1E4F95F289AF  
No fault code found.

---

VCDS-Lite  
Self-Diagnosis Log  
Wednesday, 08 March 2023, 08:58:57:51337  
Page 2

VIN Number:    License Plate:

Address 15: Airbags    Labels: 4D0-959-655-AI7.LBL  
Controller: 4D0 959 655 H  
Component: Airbag 7 Audi    050C  
Coding: 00225  
Shop #: WSC 61000  
VCID: 370160560655  
No fault code found.

---

Address 17: Instruments    Labels: 4D0-919-033-MYW.LBL  
Controller: 4D0 919 033 T  
Component: D2-KOMBIINSTRUMENT D48  
Coding: 16083  
Shop #: WSC 00000  
VCID: 351D6A5E1C59  
1 Fault Found:  
01402 - Data Wiring from Navigation System  
27-00 - Implausible Signal

---

Address 35: Centr. Locks    Labels: 8D0-862-257.LBL  
Controller: 8LO 862 257  
Component: ZV-Pumpe, DWA, Funk D03  
Coding: 13130  
Shop #: WSC 00000  
VCID: 1155FECE4871  
2 Faults Found:  
01367 - Central Locking Pump Run Time Exceeded (Likely Leak)  
35-00 - -  
01370 - Alarm triggered by Interior Monitoring  
35-00 - -

---

Address 45: Inter. Monitor    Labels: 4B0-951-173.LBL  
Controller: 8L0 951 173  
Component: Innenraumueberw. D03  
Coding: 00001  
Shop #: WSC 00000  
VCID: EEAF0532B98F  
2 Faults Found:  
01380 - Alarm triggered by Anti-Theft Sensor; Rear Left  
35-00 - -  
01381 - Alarm triggered by Anti-Theft Sensor; Rear Right  
35-00 - -

---

VCDS-Lite  
Self-Diagnosis Log  
Wednesday, 08 March 2023, 08:58:57:51337  
Page 3

VIN Number:    License Plate:

Address 02: Auto Trans    Labels: 01L-927-156.LBL

Controller: 4D0 927 156 BH

Component: AG5 01L 4.2l4V RdW 1313

Coding: 00001

Shop #: WSC 00000

VCID: 70939B4A23BB

No fault code found.

End -----