

VCDS-Lite
Windows Based VAG/VAS Emulator
Version: Release 1.2
www.Ross-Tech.com

Workshop Code: 000 00000

Self-Diagnosis Log
Thursday, 09 March 2023, 13:35:34:51337

VIN Number: License Plate:
Mileage: Repair Order:

Chassis Type: 4D - Audi A8 D2
Scan: 25,01,03,08,11,15,16,17,18,35,37,45,55,56,57,65,67,75,76,77,02

Address 25: Immobilizer Labels: 4B0-953-234.LBL
Controller: 4B0 953 234
Component: IMMO AUZ9Z0V8005539 D03
Coding: 00000
Shop #: WSC 00000
VCID: E0B36B0A735B
No fault code found.

Address 01: Engine Labels: Redir Fail!
Controller: 4D0 907 558 D
Component: 4,2L V8/4V MOTR AT D01
Coding: 05273
Shop #: WSC 51217
VCID: 2E2F4532F90F
2 Faults Found:
16684 - Random/Multiple Cylinder Misfire Detected
 P0300 - 35-10 - - - Intermittent
16685 - Cylinder 1: Misfire Detected
 P0301 - 35-10 - - - Intermittent
Readiness: N/A

Address 03: ABS Brakes Labels: 8E0-614-111-ABS.LBL
Controller: 8E0 614 111 A
Component: ABS/EDS 5.3 QUATTRO D00
Coding: 0273004284
Shop #: BB 24334
VCID: 1C4B9FFA9FB3
No fault code found.

Address 08: Auto HVAC Labels: Redir Fail!
Controller: 4D0 820 043 E
Component: D2-KLIMAVOLLAUTOMAT_D03
Coding: 00180
Shop #: WSC 00000
VCID: 1E4F95F289AF
No fault code found.

VCDS-Lite
Self-Diagnosis Log
Thursday, 09 March 2023, 13:35:34:51337
Page 2

VIN Number: License Plate:

Address 15: Airbags Labels: 4D0-959-655-AI7.LBL
Controller: 4D0 959 655 H
Component: Airbag 7 Audi 050C
Coding: 00225
Shop #: WSC 61000
VCID: 370160560655
No fault code found.

Address 17: Instruments Labels: 4D0-919-033-MYW.LBL
Controller: 4D0 919 033 T
Component: D2-KOMBIINSTRUMENT D48
Coding: 16083
Shop #: WSC 00000
VCID: 351D6A5E1C59
1 Fault Found:
01402 - Data Wiring from Navigation System
27-00 - Implausible Signal

Address 35: Centr. Locks Labels: 8D0-862-257.LBL
Controller: 8LO 862 257
Component: ZV-Pumpe, DWA, Funk D03
Coding: 13130
Shop #: WSC 00000
VCID: 1155FECE4871
2 Faults Found:
01367 - Central Locking Pump Run Time Exceeded (Likely Leak)
35-00 - -
01370 - Alarm triggered by Interior Monitoring
35-00 - -

Address 45: Inter. Monitor Labels: 4B0-951-173.LBL
Controller: 8L0 951 173
Component: Innenraumueberw. D03
Coding: 00001
Shop #: WSC 00000
VCID: EEAF0532B98F
2 Faults Found:
01380 - Alarm triggered by Anti-Theft Sensor; Rear Left
35-00 - -
01381 - Alarm triggered by Anti-Theft Sensor; Rear Right
35-00 - -

VCDS-Lite
Self-Diagnosis Log
Thursday, 09 March 2023, 13:35:34:51337
Page 3

VIN Number: License Plate:

Address 02: Auto Trans Labels: 01L-927-156.LBL
Controller: 4D0 927 156 BH
Component: AG5 01L 4.2I4V RdW 1313
Coding: 00001
Shop #: WSC 00000
VCID: 70939B4A23BB

1 Fault Found:

17087 - Brake Switch (F): Electrical Malfunction
P0703 - 35-00 - -

End -----