

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64  
VCDS Version: Release 23.3.0(x64) Data version: 20230228 DS346.1  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000 000000

Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842  
Mileage: 120617km-74947mi Repair Order:

Chassis Type: 4G-AU57 (4G8)  
Scan: 01 02 03 05 08 09 13 15 16 17 19 20 3B 3C 42 44 46 52 53 55  
5F 62 69 6C 6D 72 85 8B 8E 8F 90 AC 47

VIN: WAUZZZ4G7FN033790 Mileage: 120617km-74947miles

01-Engine -- Status: OK 0000  
02-Auto Trans -- Status: OK 0000  
03-ABS Brakes -- Status: OK 0000  
04-Steering Angle -- Status: OK 0000  
05-Acc/Start Auth. -- Status: OK 0000  
08-Auto HVAC -- Status: OK 0000  
09-Cent. Elect. -- Status: OK 0000  
13-Auto Dist. Reg -- Status: Malfunction 0010  
15-Airbags -- Status: OK 0000  
16-Steering wheel -- Status: OK 0000  
17-Instruments -- Status: Cannot be reached 0100  
19-CAN Gateway -- Status: Malfunction 0010  
20-High Beam Assist. -- Status: OK 0000  
3B-Sensor Elect. -- Status: OK 0000  
3C-Lane Change -- Status: Cannot be reached 0100  
42-Door Elect, Driver -- Status: OK 0000  
44-Steering Assist -- Status: OK 0000  
46-Central Conv. -- Status: OK 0000  
52-Door Elect, Pass. -- Status: OK 0000  
53-Parking Brake -- Status: OK 0000  
55-Headlight Range -- Status: OK 0000  
5F-Information Electr. -- Status: Malfunction 0010  
62-Door, Rear Left -- Status: OK 0000  
69-Trailer -- Status: OK 0000  
6C-Back-up Cam. -- Status: OK 0000  
6D-Trunk Elect. -- Status: OK 0000  
72-Door, Rear Right -- Status: OK 0000  
85-On Board Cam. -- Status: OK 0000  
8B-Adaptive Cruise 2 -- Status: Malfunction 0010  
8E-Image Processing -- Status: Malfunction 0010  
8F-Pretens. Frt Left -- Status: Malfunction 0010  
90-Pretens. Frt Right -- Status: Malfunction 0010  
AC-Reductant Control -- Status: OK 0000

---

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 2

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 01: Engine (J623-CRTD) Labels: 059-907-401-V2.clb  
Part No SW: 4G2 907 401 B HW: 4G2 907 401  
Component: 3.0TDI EDC17 X33 0007  
Revision: 92X33--- CVN: 72659224C2AAFDD592F1EF3C  
Coding: 12254012057601030000  
Shop #: WSC 92521 052 00000  
ASAM Dataset: EV\_ECM30TDI0114G2907401B 001007  
ROD: EV\_ECM30TDI011\_AU57.rod  
VCID: 2411E1759E5CDEDA4BB-8070  
VINID: 9D196AAAA1171D67800C31C9002DDCA3BE

No fault code found.  
Readiness: 0 0 0 0 1

-----  
Address 02: Auto Trans (J217) Labels: 0B5-927-156.clb  
Part No SW: 4G0 927 166 C HW: 0B5 927 156 K  
Component: 0B5 30 TDIRdW H03 0006  
Revision: --H03--- CVN: 00009286  
Coding: 100001  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_TCMDL501021 001021  
ROD: EV\_TCMDL501021.rod  
VCID: 2D070451CD961F92945-8078

No fault code found.

-----  
Address 03: ABS Brakes (J104) Labels: 4G0-907-379-V2.clb  
Part No SW: 4G0 907 379 Q HW: 4G0 907 379 Q  
Component: ESP9 Premium H01 0420  
Revision: ----- Serial number: -----  
Coding: 17A69E49E8657992BB00  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_ESP9BOSCHAU57X 003019  
ROD: EV\_ESP9BOSCHAU57X\_003.rod  
VCID: 3FDB4E1917FA9D02369-806A

No fault code found.

-----  
Address 05: Acc/Start Auth. (J393) Labels: 8K0-907-064-05.clb  
Part No SW: 4H0 907 064 FN HW: 4H0 907 064 EN  
Component: BCM2 2.0 H36 0551  
Revision: 00002001  
Coding: 01A9700E000000000000  
Shop #: WSC 02391 785 00200  
VCID: 7AADFF0D4CD8782A417-802E

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 3

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 08: Auto HVAC (J255) Labels:| 4G0-820-043-2Z.clb  
Part No SW: 4G0 820 043 CB HW: 4G0 820 043 CB  
Component: KLIMA 2 ZONEN H14 0112  
Serial number: 30101400110310  
Coding: 360211082D0000  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_AirCondiBasisUDS 003009  
ROD: EV\_AirCondiBasisUDS\_003.rod  
VCID: 619FA861C1CE8BF260D-8034

No fault code found.

-----  
Address 09: Cent. Elect. (J519) Labels:. 4H0-907-063-V2.clb  
Part No SW: 4H0 907 063 DH HW: 4H0 907 063 AH  
Component: BCM1 2.0 H20 0311  
Revision: 15020001 Serial number: 00000937669502  
Coding: 0105801440349FE2C101408320001800CF9CE7082E08020100000494E10115020040002D030000  
Shop #: WSC 02391 785 00200  
VCID: 71BFD82111AE3B72F0D-8024

Subsystem 1 - Part No SW: 4G1 955 119 HW: 4G8 955 119 Labels: 1KX-955-119.CLB  
Component: WWS57X 141016 H37 0080  
Serial number: 141018212818  
Coding: 004DF7

Subsystem 2 - Part No SW: 8U0 955 559 B HW: 8U0 955 559 B Labels: 8U0-955-559.CLB  
Component: G397\_RLFS H06 0002  
Serial number: 23397852  
Coding: 02006D

Subsystem 3 - Part No SW: 4G0 941 531 BE HW: 4G0 941 531 BE  
Component: E1 - LDS H07 0044  
Serial number: 15 10 2014 00001034

Subsystem 4 - Part No SW: 4G0 907 658 A HW: 4G0 907 658 A  
Component: Humidity\_Sens H03 0002  
Serial number: EC18C457000000000001

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 4

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 13: Auto Dist. Reg (J428) Labels:| 4H0-907-561.clb  
Part No SW: 4G0 907 561 B HW: 4G0 907 561  
Component: ACC3 H21 0053  
Serial number: 0000000000000000 Dataset Number: 4G0909863D 0039  
Coding: 7F04010202  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_AdaptCruisContrAU57X 002014  
ROD: EV\_AdaptCruisContrAU57X\_002.rod  
VCID: 290FF041F97E03B278D-807C

4 Faults Found:

34816 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_01]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 19 °C  
Voltage terminal 15: 13.930 V  
Velocity\_vehicle\_reference: -0.01 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35072 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_OBJLI]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 19 °C  
Voltage terminal 15: 13.930 V  
Velocity\_vehicle\_reference: -0.01 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35328 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_OBJMI]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 5

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 19 °C  
Voltage terminal 15: 13.930 V  
Velocity\_vehicle\_reference: -0.01 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35584 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

[FAULT\_CIM\_TIMEOUT\_SWA\_OBJRE]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 19 °C  
Voltage terminal 15: 13.930 V  
Velocity\_vehicle\_reference: -0.01 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

-----

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 6

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 15: Airbags (J234) Labels:\* 4H0-959-655.clb  
Part No SW: 4H0 959 655 H HW: 4H0 959 655 H  
Component: Airbag10.43 H82 0086  
Revision: ----- Serial number: 003P10023ETY Dataset Number: 4G0909602J 0005  
Coding: 30333130313930313735554A304C34473053  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_AirbaAU10BPAAU64X 001014  
ROD: EV\_AirbaAU10BPAAU64X\_VW51.rod  
VCID: 3B233A0903E281221A1-806E

Crash sensor for side airbag: driver side:  
Serial number: 3575HRB40512QP0MBGDS

Front Passenger's Side Airbag Crash Sensor:  
Serial number: 3585HRB404V2QP0MF9FE

Rear Side Airbag Crash Sensor (on driver's side):  
Serial number: 3515JRB400O52Q32CPDF

Passenger side rear thorax airbag crash sensor:  
Serial number: 3525JRB405P31QKG9HB.

Crash sensor for front airbag: driver side:  
Serial number: 3554VRB400852QV8C9S4

Crash sensor for front airbag: front passenger side:  
Serial number: 3564VRB4059327RQ89GV

No fault code found.

-----  
Address 16: Steering wheel (J527) Labels:. 4H0-953-568.clb  
Part No SW: 4H0 953 568 G HW: 4H0 953 568 G  
Component: Lenks.Modul H04 0005  
Revision: ----- Serial number: 90372NJR000BQ  
Coding: 0000FD  
Shop #: WSC 02391 785 00200  
VCID: 372B26393F4AA542FE9-8062

Subsystem 1 - Part No SW: 4G0 951 528 A HW: 4G0 951 528 A  
Component: E221 - MFL H08 0010  
Serial number: 20 10 2014 C0056199

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 7

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 17: Instruments (J285) Labels:| 4H0-920-xxx-17.clb-SRI1  
Part No SW: 4G8 920 933 F HW: 4G8 920 933 F  
Component: TDieRdwAcc H07 0043  
Revision: 03001036 Serial number: 658271014592060  
Coding: 038F12000F550008000000  
Shop #: WSC 12345 123 61029  
ASAM Dataset: EV\_RBD4K 004048  
ROD: EV\_RBD4K\_AU57.rod  
VCID: 333312292BB24962C21-8066

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 8

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 19: CAN Gateway (J533) Labels:| 4H0-907-468.clb  
Part No SW: 4G8 907 468 HW: 4G8 907 468  
Component: J533--Gateway H13 0075  
Revision: ----- Serial number: 00000001607331 Dataset Number: 4G0909515G 0018  
Coding: C0CD078118  
Shop #: WSC 02391 785 00200  
GVL: FD8DE904DCA7600F40040000  
ASAM Dataset: EV\_GatewPkoUDS 001024  
ROD: EV\_GatewPkoUDS\_001\_AU57.rod  
VCID: 75B7EC31654617522C5-8020

Battery Monitoring Control Module:  
Subsystem 1 - Part No SW: 8T0 915 181 HW: 8T0 915 181  
Component: J367-BDMHella H03 8041  
Serial number: 9468244703

Voltage stabilizer:  
Subsystem 2 - Part No SW: 8K0 959 663 F HW: 8K0 959 663  
Component: J532\_DCDCStab H23 0021  
Serial number: 1408120000000000024A

2 Faults Found:

5807 - Rear View Camera System Control Module  
U104C 00 [008] - No communication  
Intermittent - Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 2  
Fault Frequency: 1  
Reset counter: 78  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:52

Voltage terminal 30: 13.5 V  
Voltage terminal 15: 0.0 V  
Control Module temperature: 18 °C  
System status: Awake\_Timer\_active  
IN ESP\_standstill flag: standstill detected  
Engine running: OFF  
IN ZAS\_Te\_X: OFF  
Terminal 15 status via CAN: OFF  
Terminal 15 status: OFF  
Datenfeld: 0

4879 - Lane change assistant control module  
U1045 00 [009] - No communication  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 2  
Fault Frequency: 1



VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 9

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Voltage terminal 30: 13.9 V  
Voltage terminal 15: 13.8 V  
Control Module temperature: 17 °C  
System status: Terminal 15 on  
IN ESP\_standstill flag: standstill detected  
Engine running: On  
IN ZAS\_Te\_X: On  
Terminal 15 status via CAN: On  
Terminal 15 status: On  
Datenfeld: 0

---

Address 20: High Beam Assist. (J844) Labels: 8K0-857-511.clb  
Part No SW: 8T0 857 511 AD HW: 8T0 857 511 AD  
Component: FLA H04 0012  
Revision: AA001002  
Coding: 04018264747464545425363E00  
Shop #: WSC 02391 785 00200  
VCID: 7CA1F91546EC461A53B-8028

No fault code found.

---

Address 3B: Sensor Elect. (J849) Labels: 4G0-907-637.clb  
Part No SW: 4G0 907 637 K HW: 4G0 907 637 F  
Component: SARA 6D H04 0056  
Revision: ----- Serial number: EJ1BPA8208DDB6 Dataset Number: 4G0909573C 0006  
Shop #: WSC 00000 000 00000  
ASAM Dataset: EV\_SARA2 005012  
ROD: EV\_SARA2.rod  
VCID: 36352B3D38C05C4AE5F-8062

No fault code found.

---

Address 3C: Lane Change  
Cannot be reached

---

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 10

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 42: Door Elect, Driver (J386) Labels:. 4H0-959-793.clb  
Part No SW: 4G8 959 793 H HW: 4G8 959 793 F  
Component: TSG FA H04 0507  
Revision: ----- Serial number: -----  
Coding: 011F17015C00628002080013  
Shop #: WSC 02391 785 00200  
VCID: 45D75CF175A6C7D27C5-8010

No fault code found.

-----  
Address 44: Steering Assist (J500) Labels:| 4G0-909-144.clb  
Part No SW: 4G0 909 144 M HW: 4G0 909 144 G  
Component: RCEPS H41 0011  
Revision: 00001000 Serial number: 0016106199 Dataset Number: 4G0909852M 0031  
Coding: 101001010001  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_RCEPS\_009010  
ROD: EV\_RCEPS\_009.rod  
VCID: 333312292BB24962C21-8066

No fault code found.

-----  
Address 46: Central Conv. (J393) Labels:. 4H0-907-064-46.clb  
Part No SW: 4H0 907 064 FN HW: 4H0 907 064 EN  
Component: BCM2 2.0 H36 0551  
Revision: 00002001 Serial number: 0350255796  
Coding: 0100063820B93094C32009842E010F4700  
Shop #: WSC 12345 123 61029  
VCID: 7AADFF0D4CD8782A417-802E

Subsystem 1 - Part No SW: 4G9 959 591 HW: 8V3 959 591  
Component: J245 PS20.008 H02 0007  
Serial number: WOO3348387A  
Coding: 901F00

Subsystem 2 - Part No SW: 4G0 947 135 K HW: 4G0 947 135  
Component: Dachelektroni H10 0100  
Serial number: 0000000AP00009611213  
Coding: 010000

Subsystem 3 - Part No SW: 4G9 959 591 HW: 8V3 959 591  
Component: J394 PS20.008 H02 0007  
Serial number: WOO33483948  
Coding: 801F00

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 11

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 52: Door Elect, Pass. (J387) Labels: 4H0-959-792.clb  
Part No SW: 4G8 959 792 J HW: 4G8 959 792 G  
Component: TSG BF H03 0507  
Revision: ----- Serial number: -----  
Coding: 011F17015E00628002080002  
Shop #: WSC 02391 785 00200  
VCID: 46D55BFD48A0CCCA75F-8012

No fault code found.

-----  
Address 53: Parking Brake (----) Labels: 4H0-907-801.clb  
Part No SW: 4H0 907 801 H HW: 4H0 907 801 A  
Component: EPB-4 H04 0015  
Revision: ----- Serial number: 00000001250882 Dataset Number: 4G0909522E 0008  
ASAM Dataset: EV\_ParkiBrake 001028  
ROD: EV\_ParkiBrake\_VW51.rod  
VCID: 2D070451CD961F92945-8078

No fault code found.

-----  
Address 55: Headlight Range (J745) Labels: 4H4-907-357-V2.clb  
Part No SW: 4H4 907 357 D HW: 7P6 907 357 B  
Component: MxB-ECU 001 0081  
Revision: ----- Serial number: ----- Dataset Number: 4G0909865C 0014  
Coding: 04FA02102A630200  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_HeadlRegulAUDIMXBAU64X 005003  
ROD: EV\_HeadlRegulAUDIMXBAU64X\_005\_AU57.rod  
VCID: 333312292BB24962C21-8066

Left LED Headlamp Power Output Stage 1:  
Subsystem 1 - Part No SW: 7PP 941 472 J HW: 7PP 941 472 J Labels: 3D0-941-329.CLB  
Component: LED LeiMo li. H07 7560  
Coding: E01E00

Right LED Headlamp Power Output Stage 1:  
Subsystem 2 - Part No SW: 7PP 941 472 J HW: 7PP 941 472 J Labels: 3D0-941-329.CLB  
Component: LED LeiMo re. H07 7560  
Coding: E01E00

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 12

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 5F: Information Electr. (J794) Labels:| 4G1-035-MIB-HGH2.clb  
Part No SW: 4G1 035 043 M HW: 4G1 035 043  
Component: MU-H-N-EU 040 1425  
Serial number: A591J0EB003372 Dataset Number: 4G1909545B 0018  
Coding: 01750201FF0A000013110001000A00002F0006E5F17001009F  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_MUHig6C3Gen2HBAS 001115  
ROD: EV\_MUHig6C3Gen2HBAS\_AU57.rod  
VCID: 2809F545E2743ABA673-807C

Data carrier:

Subsystem 1 - Part No SW: V03 959 802 TQ HW: -----  
Component: ECE 2023 --- 0310  
Serial number: -----

Multimedia System 1:

Subsystem 2 - Part No SW: 4G1 919 605 HW: 4G1 919 605  
Component: DU8 C7 SV H42 0007  
Serial number: AUZ8Z9EL8007KM

Multimedia system control head:

Subsystem 3 - Part No SW: 4G1 919 610 F HW: 4G1 919 610 F  
Component: E380 BDT C7 H20 0250  
Serial number: 90349N JL00055

Compact disc data bank:

Subsystem 4 - Part No SW: V03 959 800 GG HW: -----  
Component: Gracenote2 --- 1021  
Serial number: -----

3 Faults Found:

1555 - Check Software Version Management  
B201A 00 [009] - -  
[Check software version management]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:  
Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:31

Voltage terminal 30: 14.3 V

Status\_Software\_Version\_Management-module\_name: MKBD\_FC7/KBD

2565 - GPS Antenna  
B1054 13 [009] - Open Circuit  
[GPS aerial - open circuit]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 13

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Fault Status: 00000001  
Fault Priority: 4  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:15:20

Voltage terminal 30: 12.9 V

7194 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

[Side assist (0x1A) - function restriction due to communication error - BapErr\_retry not successful]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:27

Voltage terminal 30: 14.3 V

BAP-BAP\_Function\_ID: 02

-----  
Address 62: Door, Rear Left (J388) Labels: 4H0-959-795.clb  
Part No SW: 4G8 959 795 J HW: 4G8 959 795 G  
Component: TSG HL H03 0507  
Revision: ----- Serial number: -----  
Coding: 010F15004000628002080002  
Shop #: WSC 02391 785 00200  
VCID: 49CF50C159BE23B298D-801C

No fault code found.

-----  
Address 69: Trailer (J345) Labels: 4H0-907-383-V2.clb  
Part No SW: 4G8 907 383 B HW: 4G8 907 383 B  
Component: Anhaenger H14 0137  
Revision: 7B001001 Serial number: 0350072978 Dataset Number: 4G0909527B 0009  
Coding: 0100000202000000  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_TrailFunctGener2Hella 001005  
ROD: EV\_TrailFunctGener2Hella\_VW26.rod  
VCID: 333312292BB24962C21-8066

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 14

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 6C: Back-up Cam. (J772) Labels:| 4S0-980-556.clb  
Part No SW: 4S0 980 556 A HW: 5Q0 980 556 B  
Component: RVC Compact H15 0201  
Dataset Number: 41073-PA -- 0014  
Coding: 0275010101002007000040  
Shop #: WSC 17873 123 50804  
ASAM Dataset: EV\_CamSysRVRVCPANAAU57X 002003  
ROD: EV\_CamSysRVRVCPANAAU57X\_002.rod  
VCID: 392F200109DEB33208D-806C

No fault code found.

-----  
Address 6D: Trunk Elect. (----) Labels:\* Redir Fail!  
Part No SW: 4G9 959 107 C HW: 4G9 959 107 B  
Component: HDSG-Modul H05 0150  
Revision: 14005001 Serial number: 283401069 Dataset Number: 4G0909541E 0004  
Coding: 093205C011  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_HDSGAu572 001022  
ROD: EV\_HDSGAu571.rod  
VCID: 36352B3D38C05C4AE5F-8062

No fault code found.

-----  
Address 72: Door, Rear Right (J389) Labels:. 4H0-959-795.clb  
Part No SW: 4G8 959 795 J HW: 4G8 959 795 G  
Component: TSG HR H03 0507  
Revision: ----- Serial number: -----  
Coding: 010F15004000628002080002  
Shop #: WSC 02391 785 00200  
VCID: 49CF50C159BE23B298D-801C

No fault code found.

-----  
Address 85: On Board Cam. (J852) Labels:| 7P6-907-217.clb  
Part No SW: 4H0 907 217 F HW: 4H0 907 217 A  
Component: DPC-SG H27 0081  
Revision: ----- Serial number: 262130025421000 Dataset Number: 4G0909547D 0007  
Coding: 6A060000  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_OnBoardCamerDPC 001007  
ROD: EV\_OnBoardCamerDPC.rod  
VCID: 2C010955F68C169A83B-8078

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 15

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 8B: Adaptive Cruise 2 (J428) Labels:| 4H0-907-561.clb  
Part No SW: 4G0 907 541 B HW: 4G0 907 541  
Component: ACC3 H21 0053  
Serial number: 000000000000000  
Coding: 7F04010202  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_AdaptCruisContr2AU57X 002012  
ROD: EV\_AdaptCruisContr2AU57X\_002.rod  
VCID: 270BF679EF6A35C26E9-8072

4 Faults Found:

34816 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_01]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 20 °C  
Voltage terminal 15: 13.712 V  
Velocity\_vehicle\_reference: -0.00 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35072 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_OBJLI]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 20 °C  
Voltage terminal 15: 13.712 V  
Velocity\_vehicle\_reference: -0.00 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35328 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_OBJMI]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

VCDS  
Self-Diagnosis Log  
Monday,20, March,2023,12:28:40:29215  
Page 16

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 20 °C  
Voltage terminal 15: 13.712 V  
Velocity\_vehicle\_reference: -0.00 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

35584 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -  
[FAULT\_CIM\_TIMEOUT\_SWA\_OBJRE]  
Confirmed - Tested Since Memory Clear  
Freeze Frame:

Fault Status: 00000001  
Fault Priority: 6  
Fault Frequency: 1  
Reset counter: 38  
Mileage: 120617 km  
Date: 2023.03.20  
Time: 12:14:24

Control Module temperature: 20 °C  
Voltage terminal 15: 13.712 V  
Velocity\_vehicle\_reference: -0.00 m/s  
Longitudinal\_acceleration\_vehicle\_reference: 0.00 m/s<sup>2</sup>

-----



VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 17

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 8E: Image Processing (J851) Labels:| 4H0-907-107-V2.clb  
Part No SW: 4H0 907 107 H HW: 4H0 907 107  
Component: BV-SG H33 0090  
Serial number: 005000622410147 Dataset Number: 4G0909548G 0008  
Coding: 04C0B91C1111  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_BC7 001001  
ROD: EV\_BC7.rod  
VCID: 2C010955F68C169A83B-8078

1 Fault Found:

0061 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

[SWA\_Timeout]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 38

Mileage: 120617 km

Date: 2023.03.20

Time: 12:14:24

Outside temperature: 4.5 °C

Voltage terminal 15: 14.0 V

Control Module temperature: 18.0 °C

---

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 18

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address 8F: Pretens. Frt Left (J854) Labels: 4H0-980-94x-RGS.clb  
Part No SW: 4H0 980 945 B HW: 4H0 980 945 C  
Component: RGS-VL H13 0080  
Dataset Number: 4G0909614C 0001  
Coding: 0066E608031F0376070308014240C2010000  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_RGS\_L 002004  
ROD: EV\_RGS\_L.rod  
VCID: 313F1821D1AE7B72B0D-8064

1 Fault Found:

12583694 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 38

Mileage: 120617 km

Date: 2023.03.20

Time: 12:14:23

---

Address 90: Pretens. Frt Right (J855) Labels: 4H0-980-94x-RGS.clb  
Part No SW: 4H0 980 946 B HW: 4H0 980 946 C  
Component: RGS-VR H13 0080  
Dataset Number: 4G0909615C 0001  
Coding: 0066E608031F0376070308014240C2010000  
Shop #: WSC 02391 785 00200  
ASAM Dataset: EV\_RGS\_R 002004  
ROD: EV\_RGS\_R.rod  
VCID: 323D172DD4A8406AC97-8066

1 Fault Found:

12583694 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 38

Mileage: 120617 km

Date: 2023.03.20

Time: 12:14:23

---

VCDS  
Self-Diagnosis Log  
Monday,20,March,2023,12:28:40:29215  
Page 19

VIN: WAUZZZ4G7FN033790 License Plate: LNC-842

Address AC: Reductant Control (J880) Labels: 4G0-907-355.clb  
Part No SW: 4G0 907 355 C HW: 4G0 907 355 B  
Component: SCR-Stg-G2 H10 0010  
Revision: 00000000 Serial number: 142821220 Dataset Number: 4G0909571F 0014  
ASAM Dataset: EV\_RDCMA00100 008040  
ROD: EV\_RDCMA00100.rod  
VCID: 2B030A49F38211A28A1-807E

No fault code found.

End------(Elapsed Time: 02:20, VBatt start/end: 13.7V/14.5V)-----